Meagan Redfern

SDMS Document ID

From:

OCARS_Pro@uncc.org

Sent:

Tuesday, May 17, 2005 2:31 PM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/05/17 #00216 B0039522-00B NORM NEW

EMLCFM 00216 UNCCb 05/17/05 02:31 PM B0039522-00B NORM NEW STRT LREQ

Ticket Nbr: B0039522-00B

Original Call Date: 05/17/05 Time: 02:31 PM Op: MRE

Locate By Date : 05/19/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City: DENVER

3310 Street: ELIZABETH ST

Grids: 03S068W25NW Legal: N

Lat/Long: 39.765142/-104.956975 39.765142/-104.955191

: 39.762573/-104.956975 39.762573/-104.955191

Type of Work: SOIL EXCAVATION

Exp.: N

Boring: N

Location: * LOC ENTIRE LOT TO INCLUDE ALL EASEMENTS TO STREET Company: PROJECT RESOURCES INC. Type: OTHR

Caller : MEAGAN REDFERN Alt Cont: AMY JAMES

Phone: (303) 487-0377 Phone: (303) 487-0377

Fax: Email: MREDFERN@PROJECTRESOURCESING.COM

Done for: CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA ATCT01 = AT&T

Members CMSND00= COMCAST - NORTH DENVER PCNDU0 = XCEL ENERGY-NORTH

DENVER

Members PSND14 = XCEL ENGY--APPT SCHEDULE-- U QLNCND0= QWEST LOCAL

NETWORK (UQ)

Members QLNCND1= QWEST LOCAL NETWORK WCG01 = WILTEL

COMMUNICATION


You are responsible for contacting any other utilities that are not

listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303) 628-6666 DNVPR1 DENVER PARKS & REC. (303) 458-4839 DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001

WWMG01 WASTEWATER MGMT DIVISION (303)446-3744





UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

999 18th STREET, SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

February 23, 2005

MELVIN L & SESIAL D HARRIS 3310 ELIZABETH ST DENVER CO 80205

RE: 3310 ELIZABETH ST #1047

Dear MELVIN L & SESIAL D:

The United States Environmental Protection Agency (EPA) has tested your property for arsenic and lead soil contamination as pert of the Vasquez Boulevard/Interstate 70 (VB/I-70) Superfund Site.

Concentrations of Arsenic and/or lead found in your soil are high enough for your property to qualify for the removal action EPA is performing this year.

ADDRESS

EPA Cleanup Level

Lead

147 parts per million (ppm)

above 400 ppm

Arsenic 78 ppm

above 70 ppm

EPA would like to remove the top layer of soil from your yard and replace it with clean soil. EPA will then re-landscape your yard to a condition similar to original. All work will be performed by EPA for free. EPA requires your consent to proceed as soon as possible. An Access Agreement that will allow the EPA to perform the soil removal work accompanies this letter. I strongly encourage you to sign this agreement and mail it back to the following address:

US EPA – VB/I-70 Project Site Attention: Victor Ketellapper 10 East 55th Avenue Denver, Colorado 80216

Your property will be scheduled for soil removal provided we promptly receive the signed Access Agreement with a telephone number where you can be contacted. EPA will coordinate the soil removal activity with you to reduce any inconvenience to you. Upon completion of the cleanup, EPA will issue a letter stating that your property has been cleaned and that no further action is necessary.

Once the attached access agreement has been received, representatives of EPA will contact you to discuss the removal of contaminated soil from your property. In the meantime, if you have further questions regarding the removal of contaminated soil at your property, please contact us at (303) 487-0377.

Sincerely,

Victor Ketellapper Remedial Project Manager United States Environmental Protection Agency (US EPA)

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Meline & le	ial Harris	Phone:
Addresses of	Address: 3310 Elin	alu H
Properties covered by	Address:	
this Agreement:	Address:	

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

Consentimiento para el Acceso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Dueño/a de la Propied	lad:	Número de Teléfono:
Dirección de las	Dirección:	
Propiedades Cubiertas por este Acuerdo:	Dirección:	
	Dirección:	

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser peligrosos a su salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgante personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgante. El Otorgante tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgante revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgante recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractores y subcontractores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Ortogante también está de acuerdo con:

 Página 1 of 2	

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my properties		☐ I do not grant access to my properties	
10 Hourst	W 52105		···
Signature	Date	Signature	Date
	resent during any sampl working sprinkler systen	ing that is required. n that will need to be replac	ed.

Page 2 of 2

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

Si, yo permito acceso a mi propiedad.		No permito acceso a mi propiedad.	
Firma	Fecha	Firma	Fecha
 ☐ Me gustaría ser presente durante de cualquier colección de muestras. ☐ Mi propiedad tiene un sistema de regar plantas y sacate (sprinkler system). 			

Página 2 of 2

PROPERTY INFORMATION		DECISION CRITERIA		
Property ID:	1047		Target Property?	Yes
House Number:	3310		Soil Sampled?	Yes
Street:	ELIZABETH ST		Removal Required?	Yes
Address:	3310 ELIZABETH ST	Find Record	Removal Complete?	
Unit:		***************************************		
ZIP Code:	80205	1	SOIL SAMPLE RI	ESULTS
Neighborhood:	CLAYTON	4	Phase 4	
Zone:	R2		Arsenic Decision Value	e 78
OWNER INFORMA	ATION		Lead Decision Value	147
Owner Name:	MELVIN L & SESIAL D HARRIS			
Mailing Address:	3310 ELIZABETH ST			
Mailing City State Zip:	DENVER CO 80205		OTHER SAMPLE	RESULTS
			Media Description	
			Arsenic	
			Lead	

mon., may 2-8:00 Am

Real Property Records

Date last updated: Friday, April 22, 2005

Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property
Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Parcel	: 0225241006000
-----------------------	-----------------

Name and Address Information	Legal Description
------------------------------	-------------------

HARRIS, MELVIN L & SESIAL D &	
	T TO 10 0 10 DI IZ 11
HADDIC DODNEY I	LTS 12 & 13 BLK 11

HARRIS, RODNE I L	MCKEES ADD
3310 ELIZABETH ST	
JJIO EEIZADEIII SI	RESIDENTIAL
DENVER, CO 80205	

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	27300	2170		
Improvements	142000	11300		
Total	169300	13470	0	13470
Prior Year				
Land	27300	2170		

э,

Page 2 of 2

11300 142000 **Improvements Total** 169300 13470 0 13470

> Style: One Story Reception No.: 0000067806

Recording Date: 06/17/92 Year Built: 1941

Document Type: Personal Rep Building Sqr. Foot: 1,096

Bedrooms: 2 Sale Price: 10

Lot Size: 6,640

Zoning: R2

Baths Full/Half: 1/0 Mill Levy: 64.402 Basement/Finished: 661/0



December 9, 2005

Memorandum For the Record

Subject: Final Inspection/Acceptance

3310 Elizabeth St.

- 1) Owner has sod issues which resulted from lack of care after the maintenance period.
- 2) The property has been inspected jointly, by the Site Co-Ordination team, the US Army Corps of Engineers Site Manager, and the contractors Site Superintendent. It has been determined, The property has been restored In accordance with the original Restoration Agreement.
- 3) No further action is deemed necessary.
- 4) This memorandum will serve as the Final Acceptance for the subject property.

Gregory P. Hoover

US Army Corps of Engineers

Site Manager





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Melvin and Sesial Harris			
Property Address	3310 Elizabeth Street			
Property Identification Number	1047			

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)			
Trees	2	\$50.00	\$100.00
Itemized shrubs/bushes	8	\$12.00	\$96.00
Total			\$196.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$196.00 has been received by the owner in the form of a replacement certificate, #15103, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature	Date	Contractor's Signature	Date

Project Besonres lac.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 1047
Property Address:
Owner:
Phone:
Restoration Items in Question:
Item:
Item:
item:
Item:
hen:
item:
Additional Comments:
That had
I agree restaration is completed, except as noted
I do not agree restoration is completed
I agree that the sprinkler system is working properly following reinstallation by contractor
· · · · · · · · · · · · · · · · · · ·
Ownex's Signature Date Contractor's Signature Date



Property Access Checklist

Property ID: 047 Property Address: 330 # Elevabeth		==	STARTED ON://_ COMPELTED ON:/_/_	
3516 14 621 16 20 16 1				
Property Owner:	esial	Property Renter:		
Mailing Address:	رد	Home Phone: 3) 377 - 8338		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Fax:		
		Cell/Page)4-19-5573		
Home Phone:		Additional Information:		
Fax:				
Cell/Pager:				
	,	 		
Notification Letter	Sent:/		By:	
Access Agreement	Signed:	<u>/_/_</u>	By:	
Restoration Agreement	Signed:	<u>//</u>	By:	
☐ Topsoil Sampling (if applicable)	/_	_/	By:	
☐ Disposal Sampling (if applicable)	/	_/	By:	
Garden Sampling (if applicable)	//		Ву:	
☐ Utility Clearance	Called://		Ву:	
☐ Video/Photos (Before)	On: <u>05</u> /	02105	By: M. Forola J. Reyo	
☐ Video/Photos (During)	On:/	/	By:	
☐ Video/Photos (After) On:/		/	By:	
☐ Video/Photos (30-Day) On:/		/	By:	
☐ Property Completion Agreement	Signed:	//	Ву:	
☐ Final Report Issu		//_	Ву:	
Air Monitoring (as applicable)				
☐ Community ☐ Crew On:// By:				
Results:				
☐ Community ☐ Crew On:	//_	By:		
Results:				
☐ Community ☐ Crew On:// By:				
Results:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 10 47	
Property Address: 3310 Clinabeth	
Owner: Melvin & Selial Harris	
Phone:	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:
Coro, flower Doto, Caro (duminum).
Item:
Caro, flower poto, cano (aluminum), tem: trash cano, ladder, bucketo,
ttem:
descrative rock
Item:
Item:
Item:
Manua
Item:
Item:



Item:


Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Cement stones on side of house by
om:
drive way leading to back porch.
m:
m:
•
m:
m:
m:
Hame To Bo Bamoved By Contractor During Bemodiation And Benjaced
items to be removed by contractor purify remediation and <u>replaced</u>
Items To Be Removed By Contractor During Remediation And <u>Replaced</u> (Use additional sheets as necessary)
(Use additional sheets as necessary) m:
(Use additional sheets as necessary) m:
(Use additional sheets as necessary) m:
(Use additional sheets as necessary) m: Clothesline Dosts
(Use additional sheets as necessary) m: Clothesline posts m: Lucy Len necess
(Use additional sheets as necessary) m: Clothesline posts m: Lucy Len necess
(Use additional sheets as necessary) m: Clothesline posts m: fure for access m:
(Use additional sheets as necessary) m: Clothesline posts m: fure for access m:
(Use additional sheets as necessary) m: Clotherline posts m: fure flor necess m:
(Use additional sheets as necessary) m: Clothesline posts m: fur for access m:
(Use additional sheets as necessary) m: Clotherline posts m: fure flor necess m:
(Use additional sheets as necessary) m: Clothesline posts m: fur for access m:



Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated		Square Feet	
Number of trees > 2 inch trunk diameter	25		
Number of trees < 2 inch trunk diameter	14		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	8		Zones:
Number of and total size of all gardens / flower	# Of Beds:		Ft ² Of Beds:
beds. Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:




ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	-	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.		SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: Brown Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:



Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large:
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		

	Additional Comments / Instructions:
)	
L	



	Additional Comments / Ir	nstructions Continued:
		ŀ
	•	
·		
		·
	•	
	•	
<u></u>	10.0	
pre-existing damage	of Owner does not want PRI to does. By checking this box PRI is	ocument interior foundation walls and possible s not responsible for any damage done to the
interior of house, in	ncluding foundation cracks or fiss	ures.
∏ agree	I do not agree	
1000	D- 0 , 105	
wid N	Vau 512105	Maria (Soutar) 5-2-05
Owner's Signature	Date	Contractor's Signature Date



6300 N. BROADWAY DENVER, COLORADO 80216

Melvin: Sesial Harris

Gift Certificate

Durchasa Data

N°	1	5	1	0	8
j.	/	o	_	_	

	i archase Date	
Presented	(· · · · · · · ·	·
to: Nellowe	sisial Harris	
CANCERS OF	196andOOcts	dollars
With Rost Wishes from	n	

THIS CERTIFICATE REDEEMABLE IN MERCHANDISE ONLY

Date Redeemed

Paulino Gardens

NOT REDEEMABLE

Garden Center and Nursery 6300 N. BROADWAY DENVER, COLORADO 80216

NOT REPLACEABLE IF LOST OR STOLEN

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1052028

	DOC	ONIENT NOMBER.
SI	TE NAME:	VASQUEZ BOULEVARD AND I-70
DO	OCUMENT DATE:	02/23/2005
Di	ue to one of the fo	DOCUMENT NOT SCANNED Blowing reasons:
	PHOTOGRAPHS	
	3-DIMENSIONAL	
	OVERSIZED	
V	AUDIO/VISUAL	
	PERMANENTLY	BOUND DOCUMENTS
	POOR LEGIBILIT	Y
	OTHER	
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DO	DOUMENT DESCR	IPTION:
	3 - DVDs OF PRO	PERTY VIDEO, PROPERTY #1047